



SURVEY PHOTO

LOCATION: Window along south façade of post 1945 construction

NUMBER: 037

COMMENTS:

South façade has noticeable outward displacement relative to window frame.

DATE: August 24, 2026





SURVEY PHOTO

LOCATION: Window along south façade of post 1945 construction

NUMBER: 038

DATE: August 24, 2026

COMMENTS:

South façade has noticeable outward displacement relative to window frame.





SURVEY PHOTO

LOCATION: Window along south façade of post 1945 construction

NUMBER: 039

DATE: August 24, 2026

COMMENTS:

South façade has noticeable outward displacement relative to window frame.





SURVEY PHOTO

LOCATION: Window along south façade of post 1945 construction

NUMBER: 040

DATE: August 24, 2026

COMMENTS:

South window frame removed to expose the concrete column supporting the second-floor framing and the cinder block load bearing wall supporting the roof structure.





SURVEY PHOTO

LOCATION: Window along south façade of post 1945 construction

NUMBER: 041

DATE: August 24, 2026

COMMENTS:

South façade window frame. Horizontally cracked stone windowsill suggesting the infiltration of water into the cavity wall system.





SURVEY PHOTO

LOCATION: North façade wall of post 1945 construction

NUMBER: 042

DATE: August 24, 2026

COMMENTS:

West view of north wall façade. Minor movement of façade wall was observed.





SURVEY PHOTO

LOCATION: North façade wall of post 1945 construction

NUMBER: 043

DATE: August 24, 2026

COMMENTS:

West view of north wall façade. Minor movement of façade wall was observed.





SURVEY PHOTO

LOCATION: North façade wall of post 1945 construction

NUMBER: 044

COMMENTS:

West view of north wall façade. Minor movement of façade wall was observed.

DATE: August 24, 2026





SURVEY PHOTO

LOCATION: North façade wall of post 1945 construction

NUMBER: 045

DATE: August 24, 2026

COMMENTS:

Sealant distress/separation around windows indicating movement of the façade. Exploratory opening in wall provided by contractor.





SURVEY PHOTO

LOCATION: North façade wall of post 1945 construction

NUMBER: 046

DATE: August 24, 2026

COMMENTS:

Western façade wall portal opening. Closer view of **Photo 045** showing outward displacement of the cinder block load bearing wall and the cavity wall construction.





SURVEY PHOTO

LOCATION: North façade wall of post 1945 construction

NUMBER: 047

DATE: August 24, 2026

COMMENTS:

Northern façade wall portal opening at west end. Similar cavity wall construction observed.





SURVEY PHOTO

LOCATION: North façade wall of post 1945 construction

NUMBER: 048

DATE: August 24, 2026

COMMENTS:

Western façade wall portal opening. Closer view of **Photo 047** showing outward displacement of the cinder block load bearing wall and the cavity wall construction.





SURVEY PHOTO

LOCATION: East façade wall of post 1945 construction

NUMBER: 049

DATE: August 24, 2026

COMMENTS:
Eastern façade wall overall view.





SURVEY PHOTO

LOCATION: E. Wilson Morrison Elementary School

NUMBER: 050

DATE: August 24, 2026

COMMENTS:

Eastern façade wall portal opening. Closer view of **Photo 049** showing outward displacement of the cinder block load bearing wall and the cavity wall construction.





SURVEY PHOTO

LOCATION: Southern façade of post 1945 construction

NUMBER: 051

DATE: August 25, 2026

COMMENTS:

Additional wall opening was created by the contractor on August 25, 2026 near the corner of the southern façade. Note the cinder block load bearing wall is essentially flush with the edge of the second-floor concrete slab.





SURVEY PHOTO

LOCATION: Interior view along south façade wall of post 1945 construction

NUMBER: 052

DATE: August 24, 2026

COMMENTS:

Existing concrete frame column and beam viewed from interior. No structural distresses observed.





SURVEY PHOTO

LOCATION: Interior view along south façade wall of post 1945 construction

NUMBER: 053

DATE: August 24, 2026

COMMENTS:

Second-floor area in library below carpet. Possible movement of cinder block wall evident based on exposed unfinished slab below carpet.





SURVEY PHOTO

LOCATION: Bathroom at southwest corner

NUMBER: 054

DATE: August 24, 2026

COMMENTS:

Second floor bathroom at far southwest corner along the south façade. No evidence of horizontal displacement as suspected by **Photo 051**.





SURVEY PHOTO

LOCATION: Bathroom at southwest corner

NUMBER: 055

DATE: August 24, 2026

COMMENTS:

Second floor bathroom at far southwest corner along the south façade. No evidence of horizontal displacement as suspected by **Photo 051**.





SURVEY PHOTO

LOCATION: Interior view along south façade of post 1945 construction

NUMBER: 056

DATE: August 24, 2026

COMMENTS:

First floor ceiling cavity space showing concrete beam and slab construction of the second-floor framing.





SURVEY PHOTO

LOCATION: Interior view along south façade of post 1945 construction

NUMBER: 057

DATE: August 24, 2026

COMMENTS:

First floor ceiling cavity space showing concrete beam and slab construction of the second-floor framing.





SURVEY PHOTO

LOCATION: Second floor Interior view along south wall of post 1945 construction

NUMBER: 058

DATE: August 24, 2026

COMMENTS:

Roof framing above second floor library reflecting newer joist construction with bulb tee tectum roof decking system.





SURVEY PHOTO

LOCATION: Second floor Interior view along south wall of post 1945 construction

NUMBER: 059

DATE: August 24, 2026

COMMENTS:

Roof framing above second floor library reflecting newer joist construction with bulb tee tectum roof decking system.





SURVEY PHOTO

LOCATION: Second floor Interior view along south wall of post 1945 construction

NUMBER: 060

DATE: August 24, 2026

COMMENTS:

Roof framing above second floor library reflecting newer joist construction with bulb tee tectum roof decking system.
Note: green arrow pointing to old joist seat remaining from original roof construction.





SURVEY PHOTO

LOCATION: Second floor Interior view along south wall of post 1945 construction

NUMBER: 061

DATE: August 24, 2026

COMMENTS:

Roof framing above second floor library reflecting newer joist construction with bulb tee tectum roof decking system.
Note: green arrow pointing to old joist seat remaining from original roof construction.





SURVEY PHOTO

LOCATION: Pipe chase below first level along south façade of post 1945 construction


NUMBER: 062

DATE: August 24, 2026

COMMENTS:

Shallow crawlspace along exterior south façade wall showing cast-in-place concrete foundation wall with no visible distress or displacement.





SURVEY PHOTO

LOCATION: Interior view along south façade wall of post 1940 construction

NUMBER: 063

DATE: August 24, 2026

COMMENTS:

Second-floor area in library below carpet. Possible movement of cinder block wall evident based on exposed unfinished slab below carpet. Also, visible separation of vertical sealant along wall and casework.





SURVEY PHOTO

LOCATION: Interior view along south façade wall of post 1940 construction

NUMBER: 064

DATE: August 24, 2026

COMMENTS:

Second floor of storage closet adjacent to library. Separation/cracking present between floor base and wall.





SURVEY PHOTO

LOCATION: Interior view along south façade wall of post 1940 construction

NUMBER: 065

DATE: August 24, 2026

COMMENTS:

Second floor of storage closet adjacent to library. Separation/cracking present between floor base and wall.

